

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG. 1



© 1965 DEL PRO






FIG. 3




FIG. 4





FIG 5



© 2002 DEL BRO

FIG 6 is a perspective view of a stone fireplace. The fireplace is constructed from irregularly shaped stones. A mantel is positioned above the fireplace opening. A door is located on the right side of the fireplace. The door is shown in an open position, revealing the interior of the fireplace. The door has a rectangular opening and is framed by a stone border. The interior of the fireplace is a large, open space. The fireplace is shown in a perspective view, with the mantel and door clearly visible.

FIG. 7




FIG 8




FIG. 9




FIG 9A

